

# Download File PDF Twi Cswip Question Answers

#Jenny



Finally I get this ebook, thanks for all these I can get now!

#Rio



Cool! I'am really happy

#Markus Jensen



I did not think that this would work, my best friend showed me this website, and it does! I get my most wanted eBook

#Hun Tsu



wtf this great ebook for free?!

#Che Salsa



My friends are so mad that they do not know how I have all the high quality ebook which they do not!

#Diego Butler



so many fake sites. this is the first one which worked! Many thanks

## Question Excerpt

1. A crack running along the centreline of a weld bead could be caused by:  
A. Use of damp flux  
B. Lack of preheat  
C. Arc voltage too high  
D. Weld bead too deep and very narrow
2. When welding this plate distortion can be minimised by:  
A. Welding from both sides  
B. Using U preparations rather than V types  
C. Using stringers  
D. Using back-step welding
3. EN ISO 5817 (Level C) specifies that the limit for the diameter (D) of a single pore in a weld is: 0.50.2t, but max. 4mm where t=material thickness. For which of the following situations is the pore acceptable?  
A. t=20mm, measured pore diameter = 5mm  
B. t=15mm, measured pore diameter = 4.5mm  
C. t=10mm, measured pore diameter = 3mm  
D. t=10mm, measured pore diameter = 1.5mm
4. Typical temperature used for normalising a C-Mn steel plate are:  
A. 600-650°C  
B. 1000-1100°C  
C. 700-800°C  
D. 880-920°C
5. The use of low carbon austenitic stainless steels and stabiliser stainless steels will minimise the risk of:  
A. HAZ cracking  
B. Weld decay  
C. Weld metal cracking  
D. Distortion
6. Transfer of material identification by hand stamping is sometimes not allowed for high integrity applications because it:  
A. Is too slow  
B. Can be a safety hazard  
C. May damage the material  
D. Causes problems with coating operations.
7. Which of the following is associated with SAW more often than it is with MMA welds?  
A. Hydrogen cracking in the HAZ  
B. Solidification cracking in the weld metal  
C. Reheat cracking during PWHT  
D. Lamellar tearing
8. A C-Mn steel is being welded by MMA and the electrode run-out lengths that have been used are much shorter than specified by the WPS. This deviation may give:  
A. Increased risk of hydrogen cracking  
B. Increased risk of solidification cracking  
C. Lower values of HAZ toughness  
D. Higher values of HAZ hardness

[Download PDF version of :](#)  
**TwI Cswip Question Answers**